

SAF-B05-014
182-F Remaining Sites – Full Protocol
FINAL VALIDATION PACKAGE

COMPLETE COPY OF VALIDATION PACKAGE TO:

Jeanette Duncan 2 copies clipped

mjl 8/16-05
INITIAL/DATE

SDG H3190

Sample Location/Waste Site: 182-F

RECEIVED
SEP 01 2005
EDMC

Date: 13 July 2005
To: Bechtel Hanford Inc. (technical representative)
From: TechLaw, Inc.
Project: 182-F Remaining Sites - Soil Full Protocol
Subject: PCB - Data Package No. H3190-LLI (SDG No. H3190)

INTRODUCTION

This memo presents the results of data validation on Summary Data Package No. H3190-LLI prepared by Lionville Laboratory Incorporated (LLI). A list of the samples validated along with the analyses reported and the method of analysis is provided in the following table.

Sample ID	Sample Date	Media	Validation	Waste Site	Analysis
J03702	5/26/05	Soil	C	182-F	PCBs by 8082
J03703	5/26/05	Soil	C	182-F	PCBs by 8082
J03704	5/26/05	Soil	C	182-F	PCBs by 8082
J03705	5/26/05	Soil	C	182-F	PCBs by 8082

Data validation was conducted in accordance with the Bechtel Hanford Incorporated (BHI) validation statement of work and the 100 Area Remedial Action Sampling and Analysis Plan (DOE/RL-96-22, Rev. 4, February 2005). Appendices 1 through 6 provide the following information as indicated below:

- Appendix 1. Glossary of Data Reporting Qualifiers
- Appendix 2. Summary of Data Qualification
- Appendix 3. Qualified Data Summary and Annotated Laboratory Reports
- Appendix 4. Laboratory Narrative and Chain-of-Custody Documentation
- Appendix 5. Data Validation Supporting Documentation

DATA QUALITY OBJECTIVES

- **Holding Times**

Sample data were assessed to ascertain whether the holding time requirements were met by the laboratory. The holding time requirements are as follows: Soil samples must be extracted within 14 days of the date of sample collection and analyzed within 40 days from the date of extraction.

000001

If holding times are exceeded by less than two times the limit, all associated sample results are qualified as estimates and flagged "J" for detects and "UJ" for non-detects. If holding times are exceeded by greater than two times the limit, all associated detected sample results are qualified as estimates and flagged "J" and all non-detects are rejected and flagged "UR".

All holding times were acceptable.

- **Method Blank**

Method blank analyses are performed to determine the extent of laboratory contamination introduced through sampling, sample preparation or analysis. At least one method blank analysis must be conducted for every 20 samples. Method blanks should not contain target compounds at a concentration greater than required quantitation limit (RQL). If target compounds are present, sample results less than five times the blank concentration are qualified as undetected and flagged "U". If the sample result is less than five times the blank concentration and less than RQL, the result is qualified as undetected and elevated to the RQL.

All method blank target compound results were acceptable.

Field Blanks

No field blanks were submitted for analysis.

- **Accuracy**

Matrix Spike & Laboratory Control Sample

Matrix spike (MS) and laboratory control sample (LCS) analyses are used to assess the analytical accuracy of the reported data. The matrix spike is used to assess the effect of the matrix on the ability to accurately quantify sample concentrations. Recoveries must fall within the range of 50% to 150% (laboratory CLP limits for chlorinated pesticides). If spike recoveries are outside control limits, detected sample results less than five times the spike concentration are qualified as estimates and flagged "J". Non-detected sample results with spike recoveries outside control limits are qualified as estimates and flagged "UJ". Sample results greater than five times the spike concentration require no qualification.

All accuracy spike results were acceptable.

000002

Surrogate Recovery

The analysis of surrogate compounds provides a measure of performance for individual samples. Matrix-specific surrogate compound recovery control windows have been established by the laboratory. When a surrogate compound recovery is outside the control window, all positively identified target compounds associated with the unacceptable surrogate recoveries are qualified as estimates and flagged "J". Non-detected compounds with surrogate recoveries less than the lower control limit are qualified as having an estimated detection limit and flagged "UJ". Non-detected compounds with surrogate recoveries above the upper control limit require no qualification.

All surrogate results were acceptable.

- **Precision**

Matrix Spike/Matrix Spike Duplicate Samples

Matrix spike/matrix spike duplicate results provide matrix-specific information on the precision of the method for specific target compound classes. Precision is expressed as the relative percent difference (RPD) between the recoveries of duplicate matrix spike analyses performed on a sample. For soil samples, results must be within RPD limits of plus/minus 30%. If RPD values are out of specification and the sample concentration is less than five times the spike concentration, all associated detected sample results are qualified as estimates and flagged "J". If RPD values are out of specification and the sample concentration is greater than five times the spike concentration, no qualification is required.

All matrix spike/matrix spike duplicate results were acceptable.

Field Duplicate Samples

No field duplicates were submitted for analysis.

- **Analytical Detection Levels**

Reported analytical detection levels are compared against the Remaining Waste Sites RQLs to ensure that laboratory detection levels meet the required criteria. All analytes met the RQL.

- **Completeness**

Data Package No. H3190-LLI was submitted for validation and verified for completeness. Completeness is based on the percentage of data determined to be valid (i.e., not rejected). The completion percentage was 100%.

MAJOR DEFICIENCIES

None found.

MINOR DEFICIENCIES

None found.

REFERENCES

BHI, MRB-SBB-A23665, *Validation Statement of Work*, Bechtel Hanford Incorporated, September 5, 1997.

DOE/RL-96-22, Rev. 4, *100 Area Remedial Action Sampling and Analysis Plan*, U.S. Department of Energy, February 2005.

000004

Appendix 1
Glossary of Data Reporting Qualifiers

000005

Qualifiers which may be applied by data validators in compliance with the procedures herein are as follows:

- U - Indicates the compound or analyte was analyzed for and not detected in the sample. The value reported is the sample quantitation limit corrected for sample dilution and moisture content by the laboratory.
- UJ - Indicates the compound or analyte was analyzed for and not detected in the sample. Due to a minor QC deficiency identified during the data validation, the associated quantitation limit is an estimate.
- J - Indicates the compound or analyte was analyzed for and detected. Due to a minor QC deficiency identified during the data validation, the associated quantitation limit is an estimate.
- R - Indicates the compound or analyte was analyzed for, detected, and due to an identified major QC deficiency, the data are unusable.
- UR - Indicates the compound or analyte was analyzed for and not detected in the sample. Additionally, the data is unusable due to an identified major QC deficiency.
- NJ - Indicates presumptive evidence of a compound at an estimated value. The data may not be valid for some specific applications (i.e., usable for decision-making purposes).
- N - Indicates presumptive evidence of a compound. The data may not be valid for some specific applications (i.e., usable for decision-making purposes).

000006

Appendix 2
Summary of Data Qualification

000007

PCB DATA QUALIFICATION SUMMARY*

SDG: H3190	REVIEWER: TLI	PROJECT: 182-F	PAGE <u>1</u> OF <u>1</u>
COMMENTS: No qualifiers assigned			

* - The Qualified Data Summary Table includes laboratory applied "U" qualifiers not specifically identified here. The laboratory applied "U" qualifiers are included to minimize misinterpretation of results contained in the table.

000008

Appendix 3

Qualified Data Summary and Annotated Laboratory Reports

Project: BECHTEL-HANFORD									
Laboratory: Lionville Laboratory Inc.									
Case:		SDG: H3190							
Sample Number		J03702		J03703		J03704		J03705	
Remarks									
Sample Date		5/26/05		5/26/05		5/26/05		5/26/05	
Extraction Date		6/6/05		6/6/05		6/6/05		6/6/05	
Analysis Date		6/9/05		6/9/05		6/9/05		6/9/05	
PCB	RQL	Result	Q	Result	Q	Result	Q	Result	Q
Aroclor-1016	20	20		13 U		14 U		14 U	
Aroclor-1221	20	14 U		13 U		14 U		14 U	
Aroclor-1232	20	14 U		13 U		14 U		14 U	
Aroclor-1242	20	14 U		13 U		14 U		14 U	
Aroclor-1248	20	14 U		13 U		14 U		14 U	
Aroclor-1254	20	20		110		14 U		14 U	
Aroclor-1260	20	14 U		13 U		23		14 U	

000010

PCBs by GC

RFW Batch Number: 0505L630

Client: TNU-HANFORD B05-014

Work Order: 11343606001 Page: 1

000071

✓
7/12/03

U= Analyzed, not detected. J= Present below detection limit. B= Present in blank. NR= Not reported. NS= Not spiked.
% = Percent recovery. D= Diluted out. I= Interference. NA= Not Applicable. * = Outside of EPA CLP QC

Appendix 4

Laboratory Narrative and Chain-of-Custody Documentation

000012



Case Narrative

Client: TNU-HANFORD D05-002

LVL #: 0505L630

SDG/SAF #: H3190/B05-014

W.O. #: 11343-606-001-9999-00

Date Received: 05-28-2005


PCB

Four (4) soil samples were collected on 05-26-2005.

The samples and their associated QC samples were extracted on 06-06-2005 and analyzed according to Lionville Laboratory SOPs based on SW846, 3rd Edition procedures on 06-09-2005. The extraction procedure was based on method 3540C and the extracts were analyzed based on method 8082.

The following is a summary of the QC results accompanying the sample results and a description of any problems encountered during their analyses:

1. All results presented in this report are derived from samples that met LVL's sample acceptance policy.
2. Samples were extracted and analyzed within required holding time.
3. The samples and their associated QC samples received a Sulfuric Acid, Copper - Sulfur, Silica Gel cleanups according to Lionville Laboratory SOPs based on SW846 method 3665A, 3660A, and 3630C respectively.
4. The method blank was below the reporting limits for all target compounds.
5. All obtainable surrogate recoveries were within acceptance criteria.
6. All blank spike recoveries were within acceptance criteria.
7. All matrix spike recoveries were within acceptance criteria.
8. The initial calibrations associated with this data set were within acceptance criteria.
9. The continuing calibration standards analyzed prior to sample extracts were within acceptance criteria with the exception of the attached Sample Discrepancy Report (SDR# 05GC235).
10. I certify that this sample data package is in compliance with SOW requirements, both technically and for completeness, other than the conditions detailed above. Release of the data contained in this hard-copy data package has been authorized by the laboratory Manager or a designee, as verified by the following signature.
11. LVL is NELAP accredited by the state of Pennsylvania and holds over 20 additional state accreditations. For a complete listing of accrediting authorities and the corresponding analytes/methods, please contact your Project Manager.


Iain Daniels
Laboratory Manager

Lionville Laboratory Incorporated

kdc:\groupdata\postnu hanford\0505-630.pcb

The results presented in this report relate only to the analytical testing and conditions of the samples at receipt and during storage. All pages of this report are integral parts of the analytical data. Therefore, this report should only be reproduced in its entirety of 8 pages.

6/22/05
Date

000013

Initiator: M. M. Mally
 Date: 6/10/05
 Client: TRC Hanford

Batch: 05052630
 Samples: 966
 Method: SVB28MCAVWVCLPI

Parameter: OP13
 Matrix: Soil
 Prep Batch: 05050467

1. Reason for SDR

a. COC Discrepancy ☐ Tech Profile Error ☐ Client Request ☐ Sampler Error on C-O-C
☐ Transcription Error ☐ Wrong Test Code ☐ Other _____

b. General Discrepancy

☐ Missing Sample/Extract ☐ Container Broken ☐ Wrong Sample Pulled ☐ Label ID's Illegible
☐ Hold Time Exceeded ☐ Insufficient Sample ☐ Preservation Wrong ☐ Received Past Hold
☐ Improper Bottle Type ☐ Not Amenable to Analysis

Note: Verified by [Log-in] or [Prep Group] (circle)...signature/date: _____

c. Problem (Include all relevant specific results; attach data if necessary)

-CCV High on LTI-CCPZ. Quantitate H13 from LTI-CCPZ.

2. Known or Probable Causes(s)

3. Discussion and Proposed Action

Other Description:

☐ Re-log
☐ Entire Batch
☐ Following Samples: _____
☐ Re-leach
☐ Re-extract
☐ Re-digest
☐ Revise EDD
☐ Change Test Code to _____
☐ Place On/Take Off Hold (circle)

Narrate + report

[Signature] 6/10/05

4. Project Manager Instructions...signature/date:

☒ Concur with Proposed Action
☐ Disagree with Proposed Action; See Instruction
☐ Include in Case Narrative
☐ Client Contacted:
 Date/Person _____
☐ Add
☐ Cancel

5. Final Action...signature/date:

Other Explanation:

☐ Verified re-[log][leach][extract][digest][analysis] (circle)
☐ Included in Case Narrative
☐ Hard Copy COC Revised
☐ Electronic COC Revised
☐ EDD Corrections Completed

When Final Action has been recorded, forward original to QA Specialist for distribution and filing.

Route Distribution of Completed SDR
☐ ☒ Initiator
☐ ☒ Lab General Manager: M. Taylor
☒ ☒ Project Mgr. Stone/Johnson/Haslett
☐ ☒ Technical Mgr. Wesson/Daniels
☐ ☒ QA (file): Alberts
☐ ☐ Data Management: Feldman
☐ ☐ Sample Prep: Beegle/Kiger

Route Distribution of Completed SDR
☐ ☐ Metals: Beegle
☐ ☐ Inorganic: Perrone
☐ ☐ GC/LC: Kiger
☐ ☐ MS: Rychlak/Layman
☐ ☐ Log-in: Melnic
☐ ☐ Admin: Soos
☐ ☐ Other: _____

Bechtel Hanford Inc.		CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST				B05-014-003		Page 1 of 1	
Collector Charlene Martinez/Jim Kiesler		Company Contact Doug Bowers		Telephone No. 531-0701		Project Coordinator KESSNER, JH		Price Code 2 D Data Turnaround	
Project Designation 182-F Remaining Sites - Soil Full Protocol		Sampling Location 182F reservoir		SAF No. B05-014		Air Quality 7 days			
Ice Chest No. HAFF ERC 99063		Field Logbook No. EI 1590		COA R118F12000		Method of Shipment Fed Ex			
Shipped To EBERLINE SERVICES (LIONVILLE)		Offsite Property No. A050 224		Bill of Lading/Air Bill No. 50850SPC					
POSSIBLE SAMPLE HAZARDS/REMARKS C DOT Limits Special Handling and/or Storage Cool 4°C 000015		Preservation Cool 4°C		A					
		Type of Container		aG					
		No. of Container(s)		1					
		Volume		250mL					
SAMPLE ANALYSIS		PCBa - 8082							
Sample No.	Matrix *	Sample Date	Sample Time						
1 J03702	SOIL	05/26/05	1020	✓					
2 J03703	SOIL	05/26/05	1040	✓					
3 J03704	SOIL	05/26/05	1055	✓					
4 J03705	SOIL	05/28/05	1120	✓					
CHAIN OF POSSESSION				SPECIAL INSTRUCTIONS				Matrix *	
Relinquished By/Removed From C. Martinez / C. Martinez		Date/Time 05/26/05		Received By/Stored In 3728 IB		Date/Time 05/26/05		Personnel not available to relinquish samples from 3728 Ref #1B on 5/27/05	
Relinquished By/Removed From REF 1B 3728		Date/Time 52705 1100		Received By/Stored In S. GALE		Date/Time 52705 1100			
Relinquished By/Removed From S. GALE		Date/Time 52705 1100		Received By/Stored In FED EX		Date/Time			
Relinquished By/Removed From F. J. E.		Date/Time 5/28/05 1025		Received By/Stored In J. H. F.		Date/Time 5/28/05 1025			
Relinquished By/Removed From		Date/Time		Received By/Stored In		Date/Time			
Relinquished By/Removed From		Date/Time		Received By/Stored In		Date/Time			
LABORATORY SECTION		Received By		Title		Date/Time			
FINAL SAMPLE DISPOSITION		Disposal Method		Disposal City		Date/Time			

Appendix 5
Data Validation Supporting Documentation

000016

PCB DATA VALIDATION CHECKLIST

VALIDATION LEVEL:	A	B	<u>C</u>	D	E
PROJECT:	182-F Rws		DATA PACKAGE: H3190		
VALIDATOR:	TLI	LAB:	LLI	DATE: 7/14/05	
			SDG:	H3190	
ANALYSES PERFORMED					
SW-846 8081	SW-846 8081 (TCLP)	<u>SW-846 8082</u>	SW-846 8081 (TCLP)		
SAMPLES/MATRIX					
J03702 J03703 J03704 J03705					
Sul					

1. DATA PACKAGE COMPLETENESS AND CASE NARRATIVE

Technical verification documentation present? Yes No N/A

Comments: _____

2. INSTRUMENT PERFORMANCE AND CALIBRATIONS (Levels D and E)

Initial calibrations acceptable? Yes No N/A

Continuing calibrations acceptable? Yes No N/A

Standards traceable? Yes No N/A

Standards expired? Yes No N/A

Calculation check acceptable? Yes No N/A

DDT and endrin breakdowns acceptable? Yes No N/A

Comments: _____

000017

PCB DATA VALIDATION CHECKLIST

3. BLANKS (Levels B, C, D, and E)

Calibration blanks analyzed? (Levels D, E) Yes No N/A
 Calibration blank results acceptable? (Levels D, E) Yes No N/A
 Laboratory blanks analyzed? Yes No N/A
 Laboratory blank results acceptable? Yes No N/A
 Field/trip blanks analyzed? (Levels C, D, E) Yes No N/A
 Field/trip blank results acceptable? (Levels C, D, E) Yes No N/A
 Transcription/calculation errors? (Levels D, E) Yes No N/A
 Comments: no FB

4. ACCURACY (Levels C, D, and E)

Surrogates analyzed? Yes No N/A
 Surrogate recoveries acceptable? Yes No N/A
 Surrogates traceable? (Levels D, E) Yes No N/A
 Surrogates expired? (Levels D, E) Yes No N/A
 MS/MSD samples analyzed? Yes No N/A
 MS/MSD results acceptable? Yes No N/A
 MS/MSD standards NIST traceable? (Levels D, E) Yes No N/A
 MS/MSD standards expired? (Levels D, E) Yes No N/A
 LCS/BSS samples analyzed? Yes No N/A
 LCS/BSS results acceptable? Yes No N/A
 Standards traceable? (Levels D, E) Yes No N/A
 Standards expired? (Levels D, E) Yes No N/A
 Transcription/calculation errors? (Levels D, E) Yes No N/A
 Performance audit sample(s) analyzed? Yes No N/A
 Performance audit sample results acceptable? Yes No N/A
 Comments: no RAS

000018

PCB DATA VALIDATION CHECKLIST

5. PRECISION (Levels C, D, and E)

Duplicate RPD values acceptable?	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> N/A
Duplicate results acceptable?	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> N/A
MS/MSD standards NIST traceable? (Levels D, E)	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A
MS/MSD standards expired? (Levels D, E)	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A
Field duplicate RPD values acceptable?	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A
Field split RPD values acceptable?	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A
Transcription/calculation errors? (Levels D, E)	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A

Comments: _____

6. SYSTEM PERFORMANCE (Levels D and E)

Chromatographic performance acceptable?	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A
Positive results resolved acceptably?	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A

Comments: _____

7. HOLDING TIMES (all levels)

Samples properly preserved?	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> N/A
Sample holding times acceptable?	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> N/A

Comments: _____

PCB DATA VALIDATION CHECKLIST

8. COMPOUND IDENTIFICATION, QUANTITATION, AND DETECTION LIMITS (all levels)

Compound identification acceptable? (Levels D, E)	Yes	No	N/A
Compound quantitation acceptable? (Levels D, E)	Yes	No	N/A
Results reported for all requested analyses?	Yes	No	N/A
Results supported in the raw data? (Levels D, E)	Yes	No	N/A
Samples properly prepared? (Levels D, E)	Yes	No	N/A
Detection limits meet RDL?	Yes	No	N/A
Transcription/calculation errors? (Levels D, E)	Yes	No	N/A

Comments: _____

9. SAMPLE CLEANUP (Levels D and E)

Fluorilicil ® (or other absorbent) cleanup performed?	Yes	No	N/A
Lot check performed?	Yes	No	N/A
Check recoveries acceptable?	Yes	No	N/A
GPC cleanup performed?	Yes	No	N/A
GPC check performed?	Yes	No	N/A
GPC check recoveries acceptable?	Yes	No	N/A
GPC calibration performed?	Yes	No	N/A
GPC calibration check performed?	Yes	No	N/A
GPC calibration check retention times acceptable?	Yes	No	N/A
Check/calibration materials traceable?	Yes	No	N/A
Check/calibration materials Expired?	Yes	No	N/A
Analytical batch QC given similar cleanup?	Yes	No	N/A
Transcription/Calculation Errors?	Yes	No	N/A

Comments: _____

000020